

# Memorandum

: Rudy Ybarra, Long Beach  
Rich Curtin, Long Beach  
John Sullivan, Woodland

Date : May 27, 1981

Subject: Underground Injection  
Control Program

From : Department of Conservation—  
Division of Oil and Gas

Place: Sacramento


To meet the terms of our Underground Injection Control (UIC) contract with the SWRCB and the EPA, the division is required to submit specific information to the SWRCB on any well that may have caused a water quality problem during 1980.

On page A-6 of our Application for Primacy in the regulation of Class II Injection Wells, the following wells apparently contributed to contamination of an underground source of drinking water (USDW).

<u>District</u>	<u>Field</u>	<u>Operator</u>	<u>Well</u>	<u>Cause</u>
1	Richfield	Texaco	YW-9	Cement failure
5	Raisin City	Crown Central	"Properties, Inc." 37-18	Cement failure
5	Riverdale	H. L. Cullivan	"Sunland-Brown" 2	Packer failure and hole
5	Riverdale	Samson Resources	"Young" D74-16	Casing and tubing holes
6	Grimes Gas	Atlantic Oil Co.	"NL&F" #1	Casing failure

Please prepare a description of the problem for the appropriate wells and also indicate the enforcement action taken or pending to correct the particular problems. A copy of the "P" and "T" reports should also be included.

If you have questions, please contact Bob Reid. The information should be submitted to Bob by June 5, 1981.

  
Simon Cordova  
Chief Deputy